

10

Manufacture to Original Size and
Shape, and Cross-Link

20

Stretch to Second Size and
Shape While Energy is Applied;
Effective^{or} Actual Temperature \geq
Transition Temperature

30

Reduce Effective^{or} Actual Temperature
While Still Stretched to Second
Size and Shape

Use

Figure 1